Subject: Re: Hum
Posted by Wayne Parham on Mon, 23 May 2005 22:43:17 GMT
View Forum Message <> Reply to Message

Wow, so the flux from the transformer was coupling over into the circuit. That's a good fix.