Subject: Re: Old Dual with motor problems
Posted by Wayne Parham on Sun, 06 Feb 2005 20:38:35 GMT
View Forum Message <> Reply to Message

Sounds like the bearing is shot and it's seizing up. The hotter it gets, the more it'll grab.