Subject: Re: Systemdek 2 bearing
Posted by DRCope on Thu, 24 Feb 2005 00:02:36 GMT
View Forum Message <> Reply to Message

It might mask the bearing noise, but I would expect it to do very strange things to the table's sound as well.Wish I could offer a helpful suggestion, but I don't know how to overcome this short of replacing the bearing, column and probably the inner platter as well. Too bad. . . .