Subject: Cartridge alignment in SME 3009 s2 improved - I'm confused!
Posted by Kuja on Tue, 21 Jun 2005 16:27:25 GMT
View Forum Message <> Reply to Message

Hello,I just bought a new Shure V15 V cartridge for my SME 3009 s2 improved.My 3009s2imp is manufactured in April 1976, serial# 212773I no longer have the original protractor.I have a question regarding the cartridge alignment null points.There is a huge confusion on the web regarding this subject!!!Here are some of the data that I have found in various scanned SME brochures or instruction manuals:Original 3009 - single null point at 2 2/3 inches (cca 70mm)3009 II - single null point at 60 mm (I've also found a document mentioning two null points - 60 & 111mm early version, 60 & 115mm later version)3009 II improved early version - single null point at 60 mm (according to two null points document mentioned earlier - two points @ 60 & 117mm)3009 II improved late version - two null points at 66 mm and 121mm3009R - two null points at 66 mm and 121mmI didn't know that there are earlier an later versions of 3009 s2 improved.Which one is mine (April 1976, serial# 212773) ?What null point settings do you recommend for it?Thanks in advance,AleksandarPS I also have lost the original 1/16" hexagonal wrench.Where can I find one? Here, we only have tools based on metric system...