Subject: Re: Shure V 15Vxmr initial disappointment. Help needed!
Posted by Manualblock on Thu, 14 Jul 2005 13:29:20 GMT
View Forum Message <> Reply to Message

Have you checked to see if his pre-amp is properly loading the cartridge? That is a classic symptom of rolled off highs.