Subject: Re: Dual CS508 Sounds terrible
Posted by Manualblock on Tue, 02 Aug 2005 08:24:28 GMT
View Forum Message <> Reply to Message

You have to use a stethoscope and place the bell end right on the sub-chassis to see if the bearing is making noise when you spin it.