Subject: CS508 Lift problems resolved...
Posted by Jsmith on Wed, 03 Aug 2005 02:15:13 GMT
View Forum Message <> Reply to Message

Thanks to a little motivation from you guys, I got the lift to operate. Im not sure why but the arm that controlled the lift pin was out of alignment. I removed the arm and reset it and eurika, the lift now functions.. Once again, thanks to manualblock and Russellc for the input. Now to change the cartridge...Thanks again guys!