Subject: Re: HELP with my Acoustic Research XA!
Posted by kevin on Tue, 09 Aug 2005 12:58:29 GMT
View Forum Message <> Reply to Message

I replaced the cartridge and there was no improvement so I borrowed my friends multimeter, and sure enough, there was no coninuity through the left RCA output. There must be either a short in the wire or something got disconnected. I'm going to open everything up today and go to work on it. Thanks for your advice.