Attach the ground wire from the table to the pre-amp chassis. The result of grounding to one RCA should make that work.If not, there's a ground loop 'tween components. Try unplugging one component at a time until the hum goes away.