Subject: Re: Garrard 401
Posted by Manualblock on Sat, 07 Jan 2006 17:54:47 GMT
View Forum Message <> Reply to Message

I would use Mobil 1 motor oil on the bearing unless you want to buy Linn's silicon based lubricant. Thats a little pricey though. You probably need to adjust the idler wheel rim-drive also. The two pins leading from the AC cord might indicate they used a seperate speed control. Have you tried the table to see if it is speed correct yet?