Subject: Re: jvc produces no sound
Posted by jvc on Sun, 22 Jan 2006 03:52:45 GMT
View Forum Message <> Reply to Message

I have it hooked to about a three year old Sony reciever. After playing with it for most of the day I can get some sound but its very soft. I've hooked up a tape deck using the same in jacks and the sound is normal. Not sure if there is something in the record player that controls output volume. Thanks.