Subject: Re: turntable surface noise in right channel
Posted by Wayne Parham on Thu, 02 Feb 2006 14:33:09 GMT
View Forum Message <> Reply to Message

Maybe check the wiring between cartridge and output jacks.