Subject: Re: Technics 1200 Output Problem
Posted by Mention on Wed, 10 May 2006 04:31:51 GMT
View Forum Message <> Reply to Message

Found the problem. One of the wires going from the tone arm into the base had somehow been cut in half. It was sticking out from under the tone arm, I dont know how I had missed it before. Thanks.