Subject: Re: grace 707 problem
Posted by gq on Thu, 08 Jun 2006 02:17:49 GMT
View Forum Message <> Reply to Message

let me try to refresh..the back side of the headshell is a spuare of either brass or copper(or that type color)there is a small finger projecting from the left side of square. from there is four leads soldered in...let me know if you have further questions because as we all know i have more time on my hands than sense!!!! if need be i can probably send a jpeg..thanxgreg