Subject: Re: Goldring 1042 troubles
Posted by Manualblock on Tue, 01 Aug 2006 14:27:29 GMT
View Forum Message <> Reply to Message

You are tracking too lightly and the cart is probably not aligned properly. Did you use an alignement guage?