Subject: Re: turntable buzz (grounding)
Posted by Bill Epstein on Sun, 10 Sep 2006 23:13:35 GMT
View Forum Message <> Reply to Message

You always hear about "Grado hum" and unshielded TT motors are a problem.But you describe static, not AC hum.ISTM that what you have is the need to change the grounding set-up of table, cartridge and arm. Is the table grounded or are you only using the ground on the cables?Add a ground from table chassis to either the phono ground or another component.The beatings will continue until morale improves