Subject: Re: turntable buzz (grounding)
Posted by Russellc on Sat, 16 Sep 2006 14:53:12 GMT
View Forum Message <> Reply to Message

Grados are unshielded, and if your motor is also unshielded, it can pick up hum from the motor. sometimes it increases as the arm moves closer to the motor.Russellc