Subject: Re: Dual 1258 and Panasonic RD9090
Posted by Wayne Parham on Tue, 14 Nov 2006 04:25:19 GMT
View Forum Message <> Reply to Message

Did you check the preamp input level? If it is set for moving coil and your cartridge has a moving magnet, that might do it. If the cartridge is ceramic, that would definitely do it.