Subject: Re: Ground or bad connection
Posted by Bill Agee on Sat, 09 Dec 2006 15:00:43 GMT
View Forum Message <> Reply to Message

I happen to have a Thorens 150 AB (not the Mark II model) that I have not used since I aquired it. However, I am preparing to rebuild it so I will take a look at how the shielding and ground is done. If I find any additional information, I'll let you know.Bill