Subject: Re: pitch control problem
Posted by Wayne Parham on Wed, 18 Jul 2007 19:49:46 GMT
View Forum Message <> Reply to Message

If your turntable is servo controlled, then the problem is likely within the PLL control circuit. Slow speeds are sometimes the result of a simple mechanical problem but fast speed usually means the servo circuit is bad. You may have to replace the servo circuit to see if that fixes it.