Subject: Re: Problem with Tascam 133
Posted by Wayne Parham on Fri, 16 Jun 2006 17:57:39 GMT
View Forum Message <> Reply to Message

Sounds like a tape head or connection to it. Examine the wires connected to the head.