Subject: Re: Sony TC-650
Posted by slbender on Fri, 13 Apr 2007 23:46:27 GMT
View Forum Message <> Reply to Message

Hi - In any 30 y/o set with permalloy heads, this could be one of ten different things, worn head, capacitor problem, internal controls, alignment, tough to guess. I have most of the remains of a TC-650, probably including a head block.-Steven