Subject: Dynaudio speaker Recon
Posted by Garrett Roach on Thu, 17 Apr 2008 05:42:30 GMT
View Forum Message <> Reply to Message

HiI have a Dynaudio 17W75EXT woofer that needs to be reconed. The voice coil rubs when presed gently in the center of the cone. Although it seems to play well when installed. It is one of the older ones. I have checked wit Madisound and Meniscus Audio and neithr can do the recone. Can any of you Audio grues help me with this.Thanks,Gary