Subject: issue
Posted by Mike.e on Wed, 25 Aug 2004 03:57:32 GMT
View Forum Message <> Reply to Message

Is this a common occurance? 'lightweight' or 'weak' higher Qts drivers in horns with high acoustic loud end up with this problem?High compression ratio,high BL driver