Subject: Re: first set of measurments
Posted by Eric Mainardi on Fri, 13 May 2005 14:51:34 GMT
View Forum Message <> Reply to Message

Hi TIM,This matches measurements I did a few months ago with my T350 from the late eighties. As they are ALNICO drivers, the slight loss of efficiency is probably due to loss of magnetization with age which is roughly around 3% per 10 year period for alnico.Very smooth and very sweet tweeter (phenolic diaphragm)ERIC