Make the area equal. Some of the T/S box analysis programs will calculate multiple ports, so they might be helpful.