Subject: Re: Newest acquisition 2 - 8" full range from Roland
Posted by roncla on Tue, 14 Sep 2004 00:39:29 GMT
View Forum Message <> Reply to Message

The pointy type pipes went out a long time ago. Its much better to make the throat (top section) at least equal to the Sd of the driver.The mouth (bottom section) should be around 4 x Sd.This will hold down ripple in given sections of the FR curve.Without T/S parameters its more or less of a crapshoot,unless you have methods to establish them.ron