Subject: Re: Newest acquisition 2 - 8" full range from Roland
Posted by roncla on Tue, 14 Sep 2004 21:09:27 GMT
View Forum Message <> Reply to Message

If the throat of a horn ,which is little more than a flared TL, has zero area (So=0)then you will get excessive ripple in the FR curve no matter what the length. Bob's sim shows what happens.Look to the left of the page and click on Voight pipes and read what the results were.ronhttp://www.geocities.com/rbrines1