Subject: Re: Isobaric
Posted by lon on Wed, 16 Feb 2005 21:35:59 GMT
View Forum Message <> Reply to Message

I just made the hookup to the little RS amp. I would say there is a problem from connecting the Yamto the tuner in on the amp. I had to jack the amp up tofull volume to get any signal at the speakers. This cannotbe right. Maybe I'd need the phono preamp connection to getany juice. But I'm not going to procede until I know more. Your suggestion sounds right though and the RS shouldbe the ideal unit without buying a new piece of gear. Maybe a y-connect from the subwwoofer out on the Yam tothe left right connects on the RS? I haven't tried the phono in to check this. What kind of damage can I do?I've already spent some dough on a repair guy tofix the RS (amp chip replacement) once for about the costof what I paid for it. :-/