Subject: Re: Opinion on the Fe127e
Posted by GM on Thu, 07 Jul 2005 15:28:33 GMT
View Forum Message <> Reply to Message

Greets!FX120 = 2 mm Xmax/~311 Hz mass corner, FE127E = 0.35 mm/~326 Hz, so it seems reasonable that this is the primary cause. Just another example of 'you get what you pay for'.GM