Subject: Re: Floor bounce
Posted by Wayne Parham on Sat, 19 May 2007 03:56:12 GMT
View Forum Message <> Reply to Message

When a driver is placed at ear height, the frequency where the floor bounce notch occurs is well above the port frequency. So port position isn't as relevent as driver position. Ceiling bounce is actually about right for the range of frequencies coming from the port though.