Subject: Re: Line Array discussion
Posted by jdybnis on Tue, 07 Sep 2004 00:14:06 GMT
View Forum Message <> Reply to Message

Interesting. If I understand this correctly it implies that a typical 5" ribbon tweeter (single, not in an array) is going to suffer from these same problems operating in its normal range (>3000Hz).