Subject: Power Tapering
Posted by Paul L. on Tue, 29 Mar 2005 06:46:58 GMT
View Forum Message <> Reply to Message

I am building an array with 10-4ohm drivers per side. I've seen people suggest a 3/2/2/3 taper, and I've read everything I can find on the subject, but I still can't get my mind to grasp the actual wiring for this set up.Can someone please explain the needed combinition of series and parallel that I will need? Final impedance is not terribly important because my amp can drive a 2ohm load without worry.Thanks