Subject: Re: K1840 for consultation
Posted by Bill Wassilak on Mon, 02 May 2005 14:18:57 GMT
View Forum Message <> Reply to Message

With those speakers you have a cone break-up modes at 7khz you'll need to tame this down, so more than likely you will need a x-over and those tweeters. Also an array this size you will have to power taper it otherwise your going to get sound bloom as they call it from sitting to standing positions.HTHBill W.