Subject: Re: Needle Array
Posted by Danse on Mon, 06 Nov 2006 19:38:12 GMT
View Forum Message <> Reply to Message

Thanks Jim!Any thoughts on: half of 4/3/2/half of 2/T/half of 2/2/3/half of 4.A little conserned at the Z = 3.3ohms, just wondering with a passive crossover the inductors should bring the Z up a bit, but would be stable enough for the amp.