Subject: Re: DCX crossover installed
Posted by jphaggar on Tue, 03 Jul 2007 17:12:12 GMT
View Forum Message <> Reply to Message

xover points are 80HZ to the subs that are not visible on this picture , 2000HZ LR 24db slope , no baffle step comp for the moment .Any suggestions ?