Subject: not yet,..working on it
Posted by atwater72 on Thu, 18 Nov 2004 12:06:49 GMT
View Forum Message <> Reply to Message

thank you for your ideas and sorry i didn't reply last time. i think the floor is the problem. its like a giant guitar sounding board. a friend is helping me redo the floor varnish and we will also cross brace underneath. after the first of the year. ill report back after were done.thanks again,atwater72