Subject: Re: Help with Grunow Model: 660 Chassis:6C
Posted by Wayne Parham on Fri, 22 Sep 2006 00:17:59 GMT
View Forum Message <> Reply to Message

One side of the potentiometer should probably be connected to ground, the other to a driver stage output and the wiper to the input of an amplifier stage.