Subject: Re: atwater kent model 42
Posted by Wayne Parham on Sun, 04 Nov 2007 21:31:12 GMT
View Forum Message <> Reply to Message

Could be any number of things but I would replace the capacitors first. The capacitors in these things are usually bad, in fact, most times the tubes still work but the caps don't. Just replace every capacitor you see with a polypropylene cap of the same value. Chances are it will fire right up.