Subject: Re: Lenco 35
Posted by Manualblock on Mon, 20 Dec 2004 13:06:29 GMT
View Forum Message <> Reply to Message

The unit is probably reverse wired. Has someone worked on it in the past?