Subject: Re: Marantz 6350Q
Posted by real_one on Tue, 27 Nov 2007 03:11:44 GMT
View Forum Message <> Reply to Message

Sounds like the servo feedback circuit fried.