Subject: Re: Fisher SA-300b volume]balance Mod
Posted by Peter Swartz on Sat, 29 Dec 2007 19:30:07 GMT
View Forum Message <> Reply to Message

Thanks Wayne, Well I decided just to forget the balance pot since I had the wrong value and hope the units outputs would be balanced. So I hooked up only the 250K volume pot and had a surprise. I obviously hooked it up wrong because it works in the opposite direction. Turning the knob clockwise turns the volume down to silence and counter-clockwise makes it louder.Any suggestions? Could it be just a matter of switching the wires on the pot?It seems to work fine. And sound fine. But sure makes me wonder if it could cause some problems.Happy New Year! Peter