Subject: Re: Trouble with marshall jcm900 2100 sl-x
Posted by Damir on Wed, 25 Jan 2006 20:23:28 GMT
View Forum Message <> Reply to Message

Seems like some problem with intermittent joint somewhere. Pull all the tubes (one by one), maybe cleaning the pins and retension of the sockets contacts can help. If not, technician help is in order...