Subject: Re: Peavey noise problem
Posted by Paul C. on Sun, 06 Aug 2006 17:26:30 GMT
View Forum Message <> Reply to Message

Turned out to be a bad cap. Replaced it and it is working well now.