Subject: Re: JC55 ROLAND / ultra compressed sound
Posted by Biggizmo54 on Mon, 25 Sep 2006 09:53:02 GMT
View Forum Message <> Reply to Message

Sounds like it is a tranformer overheat problem...or possibly a condensor meltdown. Either way, you punch your wallet into the shop time with no guarantee it wont happen again. A multiple minor problen due to a malfunction of a simple diode may prove to be costly. I suggest an alternate amplifier would be more feaseable.Depending on your sound desire, Peavey would be a good compromise at present, but there are far better lines to choose from.