Subject: Status
Posted by Wayne Parham on Tue, 27 Jul 2004 20:40:50 GMT
View Forum Message <> Reply to Message

PSD3003 replacement is still being worked on, with something hopefully ready to rollout in 6-9 months.B12 is waiting on larger rings from a new vendor, hope to have some within the month. Then those will need to be incorporated into a second prototype B12.