Subject: Re: Solid State vs Vacuum Tube Finish
Posted by Bill Martinelli on Sun, 11 Sep 2005 01:51:40 GMT
View Forum Message <> Reply to Message

You should give Varnish a try some time.You can use tung oil and let it cure for a few days, then use 3 coats of varnish. make sure to sand between coats because varnish will not burn in like a lacquer.