Subject: Re: 300B SE Project, Part 7 - Common cathode 6C45Pi triode driver
Posted by Manualblock on Sun, 26 Feb 2006 20:00:04 GMT
View Forum Message <> Reply to Message

So maybe thats why the aggressive or hard sound from the driver stage?Can a CCS loaded anode be the cause of amplifier ocsillation? Say; more so than a resistance loaded plate?