Subject: Pi Align
Posted by boblaz@yahoo.com on Fri, 28 Sep 2001 21:34:41 GMT
View Forum Message <> Reply to Message

I have run the numbers for the eminence delta 15 and the program is providing very odd numbers for the enclosure ie;cabinet: motor parameters used:encl type reflexencl vol .2222222 lo cut 30ideal fr 675 hi cut 1600ideal q .5314961 eff 101encl fr 127.9479 power 300encl q .888889 impedence 8encl ht 10.90272 quantity 1encl wd 7.268482 vas 10.4encl dp 4.845655 qd 45 frd 40