Subject: piezo buzzing when amp clips.
Posted by Andy G on Thu, 24 Jan 2002 00:27:53 GMT
View Forum Message <> Reply to Message

The piezo is protected? by (from the piezo) an 18ohm in series, then 22ohms parallel then 2µF in series. This should give some cut below 3500. When the amp clips, the piezo really buzzes, is there any way I can stop this happening??